

Tractors Maintenance

If the customer brings the machine in and picks it up, a \$125 credit will be applied to all inspection repairs.

Row Crop Tractors

9000 Series Tractors

Package 1

\$195 labor

\$225 labor

- Inspection

Package 2

\$195 labor

\$255 labor

- Change engine oil and filter
- Change fuel filter
- Change air filter
- Change transmission and hydraulic filters
- Top off with oil



Package 3

\$375 labor

\$455 labor

- Inspection
- Change engine oil and filter
- Change fuel filter
- Change air filter
- Change transmission and hydraulic filters
- Top off with oil

Oil Scan

\$95

- Kit #IPSKIT1

Do you hear a grinding or clicking noise coming from the Vari-Cool™ Fan Drive?


- For tractors equipped with a 9.0L or 13.5L engine, fan drive belt should be inspected every 500 hours or annually, whichever comes first.
- For tractors equipped with a 9.0L engine, belt should be replaced if belt is worn past 29mm.
- For tractors equipped with a 13.5L engine, belt should be replaced if belt is worn past 36mm.



Engine Damper

The engine damper reduces crankshaft torsional vibrations, which results in quieter operation, reduced crankshaft stress, reduced gear wear, reduced water pump wear, longer belt life, and longer front-drive accessory life.

Ask your Service Manager about pricing!



Parts Warranty 12 months, if installed by the dealer